

INE-F904DC / X903DC / X803DC / INE-W720DC Series

map 2020/06 and software update procedure



Update procedure for software version 1.3021

Check "Firmware Version" in Setup: → General → About → **Firmware Version**

If your Firmware Version is NOT 1.3021, please follow the instruction "UG_INE-F904x_X903x_X803x_X703x_INE-W720x_camperMAP_1000x_Instruction_EN.pdf" version.

The map 2020/06 and firmware can be updated with only one USB device and requires two update phases. First, please download the "2020-06_camperMAP_Audio.zip" and follow the instructions. The INE-F904D / X903D / X803D / X703D / INE-W720 can be updated via USB connection (see connection diagram below). Before starting the update, please check following notes. The download file is compressed in zip format. The contents of the download need to be extracted to a freshly formatted USB device (FAT32). The update takes 30 to 40 minutes.


Update file contents / storage place (for all type of units)

	Name	Größe	Typ	Änderungsdatum
> ★ Schnellzugriff				
> Dieser PC				
▼ USB-Laufwerk (F:)				
	NE000000		Dateiordner	07.07.2020 07:13
	NE00035A		Dateiordner	07.07.2020 07:14
	NE00036A		Dateiordner	07.07.2020 07:14
	NE00040A		Dateiordner	07.07.2020 07:14
	NE00041A		Dateiordner	07.07.2020 07:14

Notes



- Do NOT use the compressed file for update, otherwise the Unit cannot recognize the files.
 - Do NOT change folder name and file names, otherwise the Unit cannot recognize the files.
 - Do NOT store the folder inside another folder.
 - Do NOT store any other folders/files on the USB device.
 - Do NOT remove the USB device while updating.
 - Do NOT update while driving.
 - Do NOT press any buttons while updating.
 - Do NOT turn off vehicle's ignition or head unit's power switch while updating.
- Modern vehicles will shut down the ignition (ACC) after some time if the engine is not running.
If you are not sure if this applies to your car, leave the engine idling while the update is in progress.

Connection



Install map update (phase 1)

- 1 Store the downloaded and extracted files "2020-06_camperMap_Audio.zip" on the empty USB device in the Root Folder (see left figure).
- 2 Connect USB device to USB connector of the Alpine Head Unit. Please see lower left figure. Press "OK" button when update message appears on the screen. The process will now install the new map data to your Alpine Head Unit.



Update will be completed in around 30 minutes.

- 3 The new map data is loaded successfully when your Alpine Head Unit restarts automatically. The USB device **remains** in the Head Unit.



→ Go to no. 4.



INE-F904DC / X903DC / X803DC / INE-W720DC Series

map 2020/06 and software update procedure




Install update software (phase 2)

- 4 Then the second phase of the software update takes place.
Press **“OK”** button when update message appears on the screen. The process will now install the BU-com audio update (last part) to your Alpine Head Unit.




“Please wait” can take up to 20 seconds.

- 5 Press **“OK”** button again when next update message appears on the screen.



Update will be completed in around 3 minutes.

- 6 When the BU-com audio update is finished, the Alpine Head Unit will reboot automatically in **“Language”** select screen.




- 7 Remove the USB device from Alpine Head Unit.

- 8 Select your language and press **“OK”**.

- 9 Check **“Firmware Version”** in Setup: → General → About → **Firmware Version**
If **“Firmware Version”** number displayed as:
INE-F904DC, INE-F904DU, INE-F904S907 / -F904TRA,
X903DC-F, X903D-DU/-DU2, X903D-ID, X903D-S906,
X803DC-U, INE-W720DC:

“1.3021.1.3021.1.3021”

in SETUP menu of the Alpine Head Unit, this update procedure has been successful.



- 10 Check **“Map Version”** in Navigation → Information → About → Content → Maps
If **“Map Version”** has changed to: **“... 2020.06”**, this map update procedure has been successful.